## DEPARTMENT OF THE INTERIOR UNITED STATES GEOLOGICAL SURVEY

WRD LIBRARY
P.O. BOX 26659
ALBUQUERQUE, N. M. 87125

MAPS SHOWING GROUND-WATER CONDITIONS IN THE SAN SIMON AREA, COCHISE AND GRAHAM COUNTIES, ARIZONA, AND IN HIDALGO COUNTY, NEW MEXICO-1975

BY R. P. WILSON AND NATALIE D. WHITE

WRD, LIBRARY
P.O. BOX 26659
ALBUQUERQUE, N. M. 87125

U.S. GEOLOGICAL SURVEY
WATER-RESOURCES INVESTIGATIONS 76-89
OPEN-FILE REPORT



TUCSON, ARIZONA JULY 1976

PREPARED IN COOPERATION WITH THE ARIZONA WATER COMMISSION



## UNITED STATES DEPARTMENT OF THE INTERIOR

Water Resources Division Federal Building 301 West Congress Tucson, Arizona 85701

October 8, 1976

TO THE USERS OF GEOLOGICAL SURVEY HYDROLOGIC DATA:

Enclosed is a copy of the report entitled "Maps showing ground-water conditions in the San Simon area, Cochise and Graham Counties, Arizona, and in Hidalgo County, New Mexico--1975," by R. P. Wilson and N. D. White. The report was prepared by the U.S. Geological Survey in cooperation with the Arizona Water Commission and has been published as U.S. Geological Survey Water-Resources Investigations 76-89. Computer printouts of the hydrologic data on which the maps are based are available for consultation at the Arizona Water Commission, 222 North Central Avenue, Suite 800, Phoenix, and the U.S. Geological Survey offices in: Federal Building, 301 West Congress Street, Tucson, and Valley Center, Suite 1880, Phoenix. Material from which copies can be made at private expense is available at the Tucson and Phoenix offices of the U.S. Geological Survey.

The maps for the San Simon area are part of a series that eventually will cover the entire State. The maps show depth to water, well depth and altitude of the water level, 1975; pumpage, 1915-74; and change in water level for 1964-75, hydrographs of the water level in selected wells, specific conductance, and fluoride concentration.

Sincerely yours,

Horas m Batak

H. M. Babcock District Chief

Enclosure

RECHVED USGS WRD OCT 12 1976 ALBUQ., N. MEX.